


APPENDIX C  
POTHOLE LOGS



|                           |                       |                                 |
|---------------------------|-----------------------|---------------------------------|
| PROJECT NO.: 41-0419-11   | DATE DRILLED: 7/21/04 | NORTHING: 2292274.31            |
| LOCATION: Georgia-Pacific | LOGGED BY: M. Trevor  | EASTING: 6050681.71             |
| 90 West Redwood Avenue    | APPROVED BY: R. Batra | GROUND SURFACE ELEVATION: 42.65 |
| Fort Bragg, California    | DRILLING CO.: NA      |                                 |



Ground surface.

SILTY SAND WITH GRAVEL (SM): Reddish brown (5YR 4/3), 20% nonplastic fines, 50% sand, 30% rounded medium-grained gravel, loose.

Concrete.

SILTY SAND (SM): Yellowish red (5R 4/0), 10% nonplastic fines, 90% medium-grained sand.

- @ 5': moderate hydrocarbon odor.

GRAVELLY SAND (SP): Dark grayish brown (10YR 4/2), 70% fine- to medium-grained sand, 30% medium-grained gravel..

- @ 8': clayey sand.



**LEGEND**


☒ Sample Location



# POT HOLE




|                           |                       |                                 |
|---------------------------|-----------------------|---------------------------------|
| PROJECT NO.: 41-0419-11   | DATE DRILLED: 7/21/04 | NORTHING: 2292619.86            |
| LOCATION: Georgia-Pacific | LOGGED BY: M. Trevor  | EASTING: 6051181.04             |
| 90 West Redwood Avenue    | APPROVED BY: R. Batra | GROUND SURFACE ELEVATION: 59.98 |
| Fort Bragg, California    | DRILLING CO.: NA      |                                 |



Ground surface.  
Asphalt.

Gravel/fill.  
SAND (SP): Black (10YR 2/1), 100% fine- to medium-grained sand, very dense, damp, mild hydrocarbon odor.  
- @ 2.5': color change to light olive gray (5Y 6/2).

BEDROCK: cemented sand.



**LEGEND**


☒ Sample Location



POT HOLE



|                           |                       |                                 |
|---------------------------|-----------------------|---------------------------------|
| PROJECT NO.: 41-0419-11   | DATE DRILLED: 7/21/04 | NORTHING: 2292525.37            |
| LOCATION: Georgia-Pacific | LOGGED BY: M. Trevor  | EASTING: 6051404.00             |
| 90 West Redwood Avenue    | APPROVED BY: R. Batra | GROUND SURFACE ELEVATION: 64.11 |
| Fort Bragg, California    | DRILLING CO.: NA      |                                 |




Ground surface.

GRAVEL (GW).

SILTY SAND (SM): Black (10YR 2/1), 30% silt, 70% fine-grained sand, very dense, damp.

- @ 3': abundant wood debris.

- @ 8': wet.



**LEGEND**


☒ Sample Location



# POT HOLE




|                           |                       |                                 |
|---------------------------|-----------------------|---------------------------------|
| PROJECT NO.: 41-0419-11   | DATE DRILLED: 7/21/04 | NORTHING: 2292963.88            |
| LOCATION: Georgia-Pacific | LOGGED BY: M. Trevor  | EASTING: 6049449.24             |
| 90 West Redwood Avenue    | APPROVED BY: R. Batra | GROUND SURFACE ELEVATION: 40.06 |
| Fort Bragg, California    | DRILLING CO.: NA      |                                 |



POT HOLE




|                           |                       |                                 |
|---------------------------|-----------------------|---------------------------------|
| PROJECT NO.: 41-0419-11   | DATE DRILLED: 7/21/04 | NORTHING: 2292849.93            |
| LOCATION: Georgia-Pacific | LOGGED BY: M. Trevor  | EASTING: 6049444.38             |
| 90 West Redwood Avenue    | APPROVED BY: R. Batra | GROUND SURFACE ELEVATION: 37.20 |
| Fort Bragg, California    | DRILLING CO.: NA      |                                 |



POT HOLE




|                           |                       |                                 |
|---------------------------|-----------------------|---------------------------------|
| PROJECT NO.: 41-0419-11   | DATE DRILLED: 7/21/04 | NORTHING: 2292661.27            |
| LOCATION: Georgia-Pacific | LOGGED BY: M. Trevor  | EASTING: 6049601.65             |
| 90 West Redwood Avenue    | APPROVED BY: R. Batra | GROUND SURFACE ELEVATION: 41.40 |
| Fort Bragg, California    | DRILLING CO.: NA      |                                 |



Ground surface.


SANDY SILT (ML): Brown (7.4YR 4/2), 60% nonplastic fines, 40% medium-grained sand.

SAND (SP): Very dark brown (10YR 2/2), 100% medium-grained sand, trace gravel, loose, dry.





|                           |                       |                                 |
|---------------------------|-----------------------|---------------------------------|
| PROJECT NO.: 41-0419-11   | DATE DRILLED: 7/21/04 | NORTHING: 2292720.78            |
| LOCATION: Georgia-Pacific | LOGGED BY: M. Trevor  | EASTING: 6049620.49             |
| 90 West Redwood Avenue    | APPROVED BY: R. Batra | GROUND SURFACE ELEVATION: 45.59 |
| Fort Bragg, California    | DRILLING CO.: NA      |                                 |




Ground surface.

GRAVEL (GW): Light gray (5YR 7/1), 10% nonplastic fines, 20% medium-grained sand, 70% medium-grained gravel, loose, dry.

SANDY SILT (ML): Brown (7.4YR 4/2), 60% nonplastic fines, 40% medium-grained sand.

SAND (SP): Very dark brown (10YR 2/2), 100% medium-grained sand, trace gravel, loose, dry.




POT HOLE

P3-PH13  
PAGE 1 OF 1




|                           |                       |                                 |
|---------------------------|-----------------------|---------------------------------|
| PROJECT NO.: 41-0419-11   | DATE DRILLED: 7/21/04 | NORTHING: 2292331.44            |
| LOCATION: Georgia-Pacific | LOGGED BY: M. Trevor  | EASTING: 6050622.11             |
| 90 West Redwood Avenue    | APPROVED BY: R. Batra | GROUND SURFACE ELEVATION: 41.99 |
| Fort Bragg, California    | DRILLING CO.: NA      |                                 |



Ground surface.

SANDY SILT (ML): Dark grayish brown (10YR 4/2), 60% nonplastic fines, 40% medium-grained sand.

SILTY SAND (SM): Yellowish red (5YR 4/6), 10% nonplastic fines, 90% medium-grained sand.




POT HOLE

P3-PH14  
PAGE 1 OF 1




|                           |                       |                                 |
|---------------------------|-----------------------|---------------------------------|
| PROJECT NO.: 41-0419-11   | DATE DRILLED: 7/21/04 | NORTHING: 2292334.06            |
| LOCATION: Georgia-Pacific | LOGGED BY: M. Trevor  | EASTING: 6050641.66             |
| 90 West Redwood Avenue    | APPROVED BY: R. Batra | GROUND SURFACE ELEVATION: 43.62 |
| Fort Bragg, California    | DRILLING CO.: NA      |                                 |



Ground surface.

SANDY SILT (ML): Dark grayish brown (10YR 4/2), 60% nonplastic fines, 40% medium-grained sand.

SILTY SAND (SM): Yellowish red (5YR 4/6), 10% nonplastic fines, 90% medium-grained sand.




POT HOLE

P3-PH15  
PAGE 1 OF 1



|                           |                       |                                 |
|---------------------------|-----------------------|---------------------------------|
| PROJECT NO.: 41-0419-11   | DATE DRILLED: 7/21/04 | NORTHING: 2292276.84            |
| LOCATION: Georgia-Pacific | LOGGED BY: M. Trevor  | EASTING: 6050622.13             |
| 90 West Redwood Avenue    | APPROVED BY: R. Batra | GROUND SURFACE ELEVATION: 39.40 |
| Fort Bragg, California    | DRILLING CO.: NA      |                                 |



Ground surface.

Concrete.

GRAVEL (GW).

SAND (SP): Dark grayish brown (10YR 4/2), 100% medium-grained sand, very dense, damp.

- @ 4': slight hydrocarbon odor.

SILTY SAND (SM): Light olive gray, 10% nonplastic fines, 90% medium-grained sand.



**LEGEND**

☒ Sample Location




# POT HOLE

**P3-PH16**  
PAGE 1 OF 1



|                           |                       |  |
|---------------------------|-----------------------|--|
| PROJECT NO.: 41-0419-11   | DATE DRILLED: 7/20/04 | NORTHING: NOT SURVEYED                 |
| LOCATION: Georgia-Pacific | LOGGED BY: M. Trevor  | EASTING: NOT SURVEYED                  |
| 90 West Redwood Avenue    | APPROVED BY: R. Batra | GROUND SURFACE ELEVATION: NOT SURVEYED |
| Fort Bragg, California    | DRILLING CO.: NA      |  |

DEPTH (IN  
FEET BELOW  
GROUND  
SURFACE)



Ground surface.  
GRAVEL (GW): Very dark gray (10YR 3/1), 100% fine- to medium-grained gravel.  
BRICK.

- @ 2.5': water.  
SAND WITH GRAVEL (SP): Very dark gray (10YR 3/1), 80% fine- to medium-grained sand, 10% medium-grained gravel, abundant wood debris and organic detritus.

- @ 5.5'-8': abundant bark, hydrocarbon odor.



**LEGEND**

☒ Sample Location




POT HOLE

P4-PH1  
PAGE 1 OF 1




|                           |                       |  |
|---------------------------|-----------------------|--|
| PROJECT NO.: 41-0419-11   | DATE DRILLED: 7/20/04 | NORTHING: NOT SURVEYED                 |
| LOCATION: Georgia-Pacific | LOGGED BY: M. Trevor  | EASTING: NOT SURVEYED                  |
| 90 West Redwood Avenue    | APPROVED BY: R. Batra | GROUND SURFACE ELEVATION: NOT SURVEYED |
| Fort Bragg, California    | DRILLING CO.: NA      |  |



Ground surface.

SANDY GRAVEL (GW): Very dark brown, 30% sand, 40% gravel, 30% brick/pipe/wood debris, etc.

SAND (SP): Olive gray (5Y 5/2), 100% fine- to medium-grained sand, medium dense, wet.



**LEGEND**

⊗ Sample Location




**POT HOLE**

**P4-PH2**  
PAGE 1 OF 1



|                           |                       |                                 |
|---------------------------|-----------------------|---------------------------------|
| PROJECT NO.: 41-0419-11   | DATE DRILLED: 7/21/04 | NORTHING: 2292328.97            |
| LOCATION: Georgia-Pacific | LOGGED BY: M. Trevor  | EASTING: 6050147.81             |
| 90 West Redwood Avenue    | APPROVED BY: R. Batra | GROUND SURFACE ELEVATION: 32.08 |
| Fort Bragg, California    | DRILLING CO.: NA      |                                 |



- Ground surface.
- GRAVEL (GW): Very dark grayish brown (10YR 3/2), 100% fine- to medium-grained gravel.
- SILT (ML): Very dark grayish brown (10YR 3/2), 80% nonplastic fines, 20% fine-grained sand.
- SAND (SP): Light olive gray (5Y 6/2), 100% fine- to medium-grained sand.



**LEGEND**

⊗ Sample Location




**POT HOLE**

**P4-PH3**  
PAGE 1 OF 1




|                           |                       |                                 |
|---------------------------|-----------------------|---------------------------------|
| PROJECT NO.: 41-0419-11   | DATE DRILLED: 7/21/04 | NORTHING: 2292342.99            |
| LOCATION: Georgia-Pacific | LOGGED BY: M. Trevor  | EASTING: 6050297.82             |
| 90 West Redwood Avenue    | APPROVED BY: R. Batra | GROUND SURFACE ELEVATION: 34.15 |
| Fort Bragg, California    | DRILLING CO.: NA      |                                 |



Ground surface.

GRAVELLY SILT (ML): Very dark grayish brown (10YR 3/2), 70% nonplastic fines, 30% fine- to medium-grained gravel.

SAND (SP): Light olive gray (5Y 6/2), 100% fine- to medium-grained sand.



- @ 9.5': wet.



**LEGEND**

⊗ Sample Location




**POT HOLE**

**P4-PH4**  
PAGE 1 OF 1



|                           |                       |                                 |
|---------------------------|-----------------------|---------------------------------|
| PROJECT NO.: 41-0419-11   | DATE DRILLED: 7/20/04 | NORTHING: 2291627.48            |
| LOCATION: Georgia-Pacific | LOGGED BY: M. Trevor  | EASTING: 6050970.55             |
| 90 West Redwood Avenue    | APPROVED BY: R. Batra | GROUND SURFACE ELEVATION: 50.70 |
| Fort Bragg, California    | DRILLING CO.: NA      |                                 |

DEPTH (IN  
FEET BELOW  
GROUND  
SURFACE)



Ground surface.

GRAVEL (GW): Light gray (2.5Y 1/1), 20% nonplastic fines, 80% fine- to coarse-grained angular gravel, damp.

SILTY SAND (SM): Dark yellowish brown (10YR 3/4) to olive brown (2.5Y 4/4) to greenish gray (5GY 6/1), 20% nonplastic fines, 80% fine- to medium-grained sand, damp.

- @ 5': color change to olive gray; moderate hydrocarbon odor.

- @ 8': color change to dark olive gray; strong hydrocarbon odor.

- @ 10.5': bedrock.

PLAN VIEW



**LEGEND**

⊗ Sample Location




**POT HOLE**

**P5-PH1**  
PAGE 1 OF 1




|                           |                       |                                 |
|---------------------------|-----------------------|---------------------------------|
| PROJECT NO.: 41-0419-11   | DATE DRILLED: 7/21/04 | NORTHING: 2291733.98            |
| LOCATION: Georgia-Pacific | LOGGED BY: M. Trevor  | EASTING: 6051216.94             |
| 90 West Redwood Avenue    | APPROVED BY: R. Batra | GROUND SURFACE ELEVATION: 58.13 |
| Fort Bragg, California    | DRILLING CO.: NA      |                                 |



POT HOLE




|                           |                       |                                 |
|---------------------------|-----------------------|---------------------------------|
| PROJECT NO.: 41-0419-11   | DATE DRILLED: 7/21/04 | NORTHING: 2291805.22            |
| LOCATION: Georgia-Pacific | LOGGED BY: M. Trevor  | EASTING: 6051256.48             |
| 90 West Redwood Avenue    | APPROVED BY: R. Batra | GROUND SURFACE ELEVATION: 58.01 |
| Fort Bragg, California    | DRILLING CO.: NA      |                                 |





|                           |                       |                                 |
|---------------------------|-----------------------|---------------------------------|
| PROJECT NO.: 41-0419-11   | DATE DRILLED: 7/20/04 | NORTHING: 2291645.53            |
| LOCATION: Georgia-Pacific | LOGGED BY: M. Trevor  | EASTING: 6051018.06             |
| 90 West Redwood Avenue    | APPROVED BY: R. Batra | GROUND SURFACE ELEVATION: 50.45 |
| Fort Bragg, California    | DRILLING CO.: NA      |                                 |



Ground surface.

GRAVEL (GW): Light gray (2.5Y 1/1), 20% nonplastic fines, 80% fine- to coarse-grained angular gravel, damp, moderate hydrocarbon odor.

SAND (SP): Light olive gray, 20% nonplastic fines, 80% fine- to medium-grained sand, damp, moderate hydrocarbon odor.

- @ 8': bedrock: cemented sand.



**LEGEND**

⊗ Sample Location




**POT HOLE**

**P5-PH4**  
PAGE 1 OF 1



|                           |                       |                                 |
|---------------------------|-----------------------|---------------------------------|
| PROJECT NO.: 41-0419-11   | DATE DRILLED: 7/20/04 | NORTHING: 2291646.93            |
| LOCATION: Georgia-Pacific | LOGGED BY: M. Trevor  | EASTING: 6051086.29             |
| 90 West Redwood Avenue    | APPROVED BY: R. Batra | GROUND SURFACE ELEVATION: 51.18 |
| Fort Bragg, California    | DRILLING CO.: NA      |                                 |




# POT HOLE




|                           |                       |                                 |
|---------------------------|-----------------------|---------------------------------|
| PROJECT NO.: 41-0419-11   | DATE DRILLED: 7/20/04 | NORTHING: 2291565.06            |
| LOCATION: Georgia-Pacific | LOGGED BY: M. Trevor  | EASTING: 6051105.85             |
| 90 West Redwood Avenue    | APPROVED BY: R. Batra | GROUND SURFACE ELEVATION: 52.93 |
| Fort Bragg, California    | DRILLING CO.: NA      |                                 |

DEPTH (IN  
FEET BELOW  
GROUND  
SURFACE)



- Ground surface.
- GRAVEL (GW): Light gray (2.5Y 1/1), 20% nonplastic fines, 80% fine- to coarse-grained angular gravel, damp.
- @ 1.5'-3.5': gray discoloration, strong hydrocarbon odor.
- SAND (SP): Light olive gray, 20% nonplastic fines, 80% fine- to medium-grained sand, damp.
- @ 8': wet; bedrock: cemented sand.



**LEGEND**

☒ Sample Location




POT HOLE

P5-PH6  
PAGE 1 OF 1



|                           |                       |                                 |
|---------------------------|-----------------------|---------------------------------|
| PROJECT NO.: 41-0419-11   | DATE DRILLED: 7/20/04 | NORTHING: 2291785.99            |
| LOCATION: Georgia-Pacific | LOGGED BY: M. Trevor  | EASTING: 6050964.04             |
| 90 West Redwood Avenue    | APPROVED BY: R. Batra | GROUND SURFACE ELEVATION: 50.40 |
| Fort Bragg, California    | DRILLING CO.: NA      |                                 |

DEPTH (IN  
FEET BELOW  
GROUND  
SURFACE)



Ground surface.

GRAVEL (GW): Light gray (2.5Y 1/1), 20% nonplastic fines, 80% fine- to coarse-grained angular gravel, damp.

- @ 2.0'-5.0': darker.



SAND (SP): Brown (10YR 5/3), 100% fine- to medium-grained sand, faint hydrocarbon odor to 8'.

- @ 8': wet; no odor past 8'.



**LEGEND**



Sample Location




POT HOLE

P5-PH7  
PAGE 1 OF 1




|                           |                       |                                 |
|---------------------------|-----------------------|---------------------------------|
| PROJECT NO.: 41-0419-11   | DATE DRILLED: 7/20/04 | NORTHING: 2291701.43            |
| LOCATION: Georgia-Pacific | LOGGED BY: M. Trevor  | EASTING: 6050915.62             |
| 90 West Redwood Avenue    | APPROVED BY: R. Batra | GROUND SURFACE ELEVATION: 49.75 |
| Fort Bragg, California    | DRILLING CO.: NA      |                                 |



POT HOLE




|                           |                       |                                 |
|---------------------------|-----------------------|---------------------------------|
| PROJECT NO.: 41-0419-11   | DATE DRILLED: 7/21/04 | NORTHING: 2291395.08            |
| LOCATION: Georgia-Pacific | LOGGED BY: M. Trevor  | EASTING: 6049966.49             |
| 90 West Redwood Avenue    | APPROVED BY: R. Batra | GROUND SURFACE ELEVATION: 49.76 |
| Fort Bragg, California    | DRILLING CO.: NA      |                                 |






|                           |                       |                                 |
|---------------------------|-----------------------|---------------------------------|
| PROJECT NO.: 41-0419-11   | DATE DRILLED: 7/20/04 | NORTHING: 2291480.81            |
| LOCATION: Georgia-Pacific | LOGGED BY: M. Trevor  | EASTING: 6049334.49             |
| 90 West Redwood Avenue    | APPROVED BY: R. Batra | GROUND SURFACE ELEVATION: 44.61 |
| Fort Bragg, California    | DRILLING CO.: NA      |                                 |



POT HOLE




|                           |                       |                                 |
|---------------------------|-----------------------|---------------------------------|
| PROJECT NO.: 41-0419-11   | DATE DRILLED: 7/21/04 | NORTHING: 2291514.30            |
| LOCATION: Georgia-Pacific | LOGGED BY: M. Trevor  | EASTING: 6049863.58             |
| 90 West Redwood Avenue    | APPROVED BY: R. Batra | GROUND SURFACE ELEVATION: 52.58 |
| Fort Bragg, California    | DRILLING CO.: NA      |                                 |





|                           |                       |                                 |
|---------------------------|-----------------------|---------------------------------|
| PROJECT NO.: 41-0419-11   | DATE DRILLED: 7/20/04 | NORTHING: 2288442.76            |
| LOCATION: Georgia-Pacific | LOGGED BY: M. Trevor  | EASTING: 6050055.72             |
| 90 West Redwood Avenue    | APPROVED BY: R. Batra | GROUND SURFACE ELEVATION: 85.63 |
| Fort Bragg, California    | DRILLING CO.: NA      |                                 |



POT HOLE